

A/C COMPRESSOR REPLACEMENT DONE RIGHT.

Replacing an A/C compressor may not be a one part repair, but it doesn't have to be complicated. Most technicians know to also replace the receiver drier to restart the system with fresh desiccant while the system is open; however, driers only help with moisture.

With every compressor replacement there is a good chance you'll see debris and contaminated PAG oil throughout the system that must be addressed. Therefore, the condenser, where a lot of the debris and acidic contaminated PAG oil is trapped, is also a critical part of a compressor replacement.

DID YOU KNOW?

PARALLEL FLOW CONDENSERS CAN'T BE FLUSHED!

Putting a new compressor inline with a condenser that was connected to a failed compressor will likely lead to early failure.

By replacing the receiver drier AND condenser with every new compressor, you're getting a proven long-term system of reliable cooling performance.

FLUSH THE A/C LINES EVERY TIME

A/C Flush Kits are excellent at removing contaminants and acidic oil from A/C lines. The A/C Flush Gun is quick, easy, and safe to use, complete with an attached flow control valve.



HEAVY-DUTY A/C FLUSH KIT (ACT6807) FEATURES:

- 32 oz Premium Flush Solvent
- Shut-Off / Pressure Control Valve
- Shop Hose Adapter
- Can be used without shop hose

OEM	ENGINE	YEAR	COMPRESSOR	CONDENSER	DRIER
VOLVO / MACK	D13 (VOLVO) MP8 (MACK)	2009 - 2017 ½	ACC3414 OE# 20721587	CON1426 OE# 22314813	RD12095 OE# 82781559
		2017 ½ - 2023	ACC3417 OE# 82768117	CON1432 OE# 22386057	RD15800 OE# 82771584
FREIGHTLINER CASCADIA	DD13, 15, 16	2010 - 2020	ACC1275 OE# 22-65771-001	DAY CAB CON0429 OE# A22-72459-000	RD11222 OE# A22-77123-003
				SLEEPER CAB CON0431 OE# A22-72460-000	
FREIGHTLINER CASCADIA	DD13, 15, 16	2018 - 2024	ACC1275 OE# 22-65771-001	DAY CAB CON0439 OE# A22-72869-000	RD11225 OE# A22-77123-000
				SLEEPER CAB CON0438 OE# A22-72870-000	